

SECTION 00942 - Change Order Form

No. 1

DATE OF ISSUANCE: 12/17/2024

EFFECTIVE DATE: 12/17/2024

OWNER: Indian River County

CONTRACTOR Southeast Services of the Treasure Coast, Inc.

Project: CR512 & N. Broadway St. Drainage Restoration (Fellsmere)

OWNER's Project No. IRC-2006

OWNER'S Bid No. 2024036

You are directed to make the following changes in the Contract Documents:

Description:

Raising buried manholes, internal grouting to fill and repair pipe surface defects and external pressure grouting of branch connections to the CR512 main drainage line.

Reason for Change Order:


Defects discovered during cleaning and video inspection of pipes.


Attachments:

Southeast Services, Inc. Estimate No. 6339, dated 12/3/2024

CHANGE IN CONTRACT PRICE:	
Description	Amount
Original Contract Price	<u>\$215,234.70</u>
Net increase (decrease) of this Change Order:	<u>\$211,108.00</u>
Contract Price with all approved Change Orders:	<u>\$426,342.70</u>

CHANGE IN CONTRACT TIMES	
Description	Time
Original Contract Time:	(days or dates)
Final Completion:	<u>180</u>
Net increase (decrease) this Change Order:	(days or dates)
Final Completion:	<u>44</u>
Contract Time with all approved Change Orders:	(days or dates)
Final Completion:	<u>224</u>

ACCEPTED: 
By: Southeast Services, Inc. CONTRACTOR (Signature)
Date: <u>12-4-24</u>

RECOMMENDED: 
By: Mark Winslow, P.E. ENGINEER (Signature)
Date: <u>12/3/24</u>

APPROVED:
By: Joseph E. Flescher, Chairman OWNER (Signature)
Date:

ESTIMATE

Southeast Services of the
Treasure Coast, Inc. CG
815 10th Court SW
Vero Beach, FL 32962

seservices@bellsouth.net
+1 (772) 226-7416



Bill to

Indian River County Florida
1800 27th Street
Vero Beach, FL 32960

Ship to

Indian River County Florida
1800 27th Street
Vero Beach, FL 32960

Estimate details

Estimate no.: 6339
Estimate date: 12/03/2024

P.O. Number: Storm Water repairs
Job Number: IRC-2006
Job Location: C.R. 512 & N.Broadway
Fellsmere

#	Date	Product or service	Description	Qty	Rate	Amount
1.		Asset Repair	Southeast Services proposes the following repairs to the storm water system, pricing is inclusive of mobilization, materials, labor, and post repair TV inspection.			
2.		Asset Repair	I-21 to I-20 (P29) grout joint at 15.5' grout hole in pipe at 4 o'clock at 32.3' grout hole in pipe at 9 o'clock at 40.6' I-21 to 8 (P30) grout joint at 11.2' grout defect at 15.1' grout defect at 23.4' grout defect at 12 o'clock at 38.9' (1) day.	1	\$5,400.00	\$5,400.00
3.		Asset Repair	I-24 to MH 9 (P35) grout defect at 8 o'clock at 70.4' grout defect at 4 o'clock at 78.5' grout defect at 4 o'clock at 95.5' grout defect at 3 o'clock at 98.8' remove scale and grout at 99.1' grout joint at 100.1' (1) day.	1	\$5,400.00	\$5,400.00
4.		Asset Repair	I-28 to MH 10 grout defect at 7 o'clock at 14.5' grout defect at 7 o'clock at 22.2' grout defect at 7 o'clock at 30.1' grout defect at 11 o'clock at 47.1' grout defect at 2 o'clock at 55.8 ' grout defect at 7 o'clock at 64.7'	2	\$5,400.00	\$10,800.00

		grout joint at 68.9' grout defect at 7 o'clock at 72.8' grout defect at 7 o'clock at 78.5' grout defect at 2 o'clock at 81' grout defect at 7 o'clock at 88.6' grout defect at 7 o'clock at 105.1' (2) days			
5.	Asset Repair	I-30 to I-29 grout defect at 8 o'clock at 22.7' grout defect at 10 o'clock at 38.6' grout defect at 3 o'clock at 45.6' I-30 to MH 10 grout defect at 3 o'clock at 12.6' grout defect at 9 o'clock at 21' grout defect at 12 o'clock at 27.7' grout defect at 9 o'clock at 36.5' (1) day	1	\$5,400.00	\$5,400.00
6.	Asset Repair	I-33 to I-32 grout joint at 9' grout defect at 4 o'clock at 13.8' grout defect at 2 o'clock at 21.7' grout joint at 25.5' grout defect at 38' (1) day	1	\$5,400.00	\$5,400.00
7.	Asset Repair	I-33 to MH 11 grout defect at 12 o'clock at 12' grout defect at 12 o'clock at 19.2' grout joint at 25' grout defect at 3 o'clock at 49' grout defect at 3 o'clock at 54.6' grout defect at 3 o'clock at 62.5' grout defect at 2 o'clock at 70.1' grout defect at 4 o'clock at 79.4' grout defect at 3 o'clock at 100' (2) days	2	\$5,400.00	\$10,800.00
8.	Asset Repair	MH 11 to MH 12 grout at 133.6' grout at 166' (1) day	1	\$5,400.00	\$5,400.00
9.	Asset Repair	I-19 to MH 8 (P28) Inclusive of chain cutting grout defect at 14.3' grout defect at 22.1' grout old lift ring at 30' (chain cut) grout defect at 38.1' (chain cut) grout lift ring hole at 46.4' grout lift ring hole at 55.9' grout hole at 6 o'clock at 62.4' grout hole in joint (I&I) at 66.9' grout hole at 9 o'clock at 70.5' grout joint out of tolerance at 74.9' grout hole at 7 o'clock at 78.4' grout joint out of tolerance (I&I) at 82.9' grout joint out of tolerance at 91.1' (4) days	4	\$5,400.00	\$21,600.00
10.					

	Asset Repair	MH 6 to MH 7 Chain cut and grout at 183' (2) days	2	\$5,400.00	\$10,800.00
11.	Asset Repair	I-9 to I-10 (P-14) grout hole at 6 o'clock at 20' grout hole at 2 o'clock at 28.5' grout hole at 9 o'clock at 36.1' grout hole at 2 o'clock at 45.2' I-10 to MH 5 No access concrete in pipe. (1) day	1	\$5,400.00	\$5,400.00
12.	Asset Repair	I-8 to MH 5 (P-13) grout hole at 4 o'clock at 22' grout hole at 6 o'clock at 29' grout hole at 10 o'clock at 37' grout hole at 6 o'clock at 45' grout hole at 7 o'clock at 50' grout hole at 3 o'clock at 52' install interior band at 66' grout hole at 2 o'clock at 70' grout hole at 4 o'clock at 77' grout hole at 7 o'clock at 85' grout hole at 2 o'clock at 92' (2) days	2	\$5,400.00	\$10,800.00
13.	Asset Repair	I-7 to I-8 install band at 21' (1) day	1	\$5,400.00	\$5,400.00
14.	Asset Repair	P-12 grout hole at 7 o'clock at 25.3' (1) day	1	\$5,400.00	\$5,400.00
15.	Asset Repair	I-16 to I-17 (P-24) grout hole at 15' (roots I&I) grout hole at 3 o'clock at 23' (I&I) grout hole at 11 o'clock at 40' (I&I) (1) day	1	\$5,400.00	\$5,400.00
16.	Asset Repair	I-17 to MH 7 (P-25) grout at 67' (heavy I&I at I-17) I-13 to I-14 (P-21) concrete wire blocking at I-13 (1) day	1	\$5,400.00	\$5,400.00
17.	Asset Repair	I-15 to MH 7 (P-23) grout hole at 3 o'clock at 53' grout hole at 3 o'clock at 60' grout hole at 9 o'clock at 84.5' grout hole at 9 o'clock at 93' (1) day	1	\$5,400.00	\$5,400.00
18.	Asset Repair	I-26 to I -25 (P-36) (SD 26 to SD 25) grout hole at 3 o'clock at 16.1' grout hole at 2 o'clock at 23.6' grout hole at 7 o'clock at 31.4' grout joint at 35.4' grout hole at 9 o'clock at 40' (1) day	1	\$5,400.00	\$5,400.00

19.	Asset Repair	SD -26 to MH 9 (P-37) (I-26 to MH 9) grout hole at 7 o'clock at 2' grout hole at 7 o'clock at 16' grout hole at 7 o'clock at 24.2' grout hole at 6 o'clock at 31.5' (1 day)	1	\$5,400.00	\$5,400.00
20.	Asset Repair	SD-24 to SD -23 (P-34) grout hole at 11 o'clock at 15.1' grout hole at 10 o'clock at 23.2' grout hole at 5 o'clock at 38.4' (1) day	1	\$5,400.00	\$5,400.00
21.	Asset Repair	I-19 to I-18 (P-27) grout hole at 7 o'clock at 14' grout hole at 7 o'clock at 22.1' grout hole at 1 o'clock at 30.4' grout hole at 9 o'clock at 38.6' (1) day	1	\$5,400.00	\$5,400.00
22.	Asset Repair	I-35 to MH 11 (P-50) install band at joint at 40.5' (1) day	1	\$5,400.00	\$5,400.00
23.	Asset Repair	I-28 to I-27 (P-39) grout hole at 3 o'clock at 23.5' grout hole at 1 o'clock at 31' (1) day	1	\$5,400.00	\$5,400.00
24.	Asset Repair	I-37 to MH 12 (P-55) grout hole at 12 o'clock at 27.5' grout hole at 7 o'clock at 45.3' grout hole at 7 o'clock at 42.5' grout hole at 4 o'clock at 70' (1) day	1	\$5,400.00	\$5,400.00
25.	Asset Repair	I-36 to I-37 (P-54) grout hole at 3 o'clock at 14' grout hole at 9 o'clock at 36' (1) day	1	\$5,400.00	\$5,400.00
26.	Asset Repair	I-39 to I-40 (P-60) grout hole at 11 o'clock at 7.3' grout joint out of tolerance at 20.5' grout joint at 29' (I&I) (1) day	1	\$5,400.00	\$5,400.00
27.	Asset Repair	I-38 to MH 13 grout hole at 8 o'clock at 12.4' grout hole at 9 o'clock at 19.5' grout hole at 8 o'clock at 28.2' grout hole at 10 o'clock at 36.5' grout hole at 8 o'clock at 44.8' grout hole at 4 o'clock at 53' grout hole at 12 o'clock at 61.2' (1) day	1	\$5,400.00	\$5,400.00
28.	Asset Repair	I-38 to catch basin (P-59C) grout hole at 2 o'clock at 10.9' grout hole at 2 o'clock at 17.9' grout hole at 4 o'clock at 35.7'	1	\$5,400.00	\$5,400.00

grout hole at 4 o'clock at 52.3'
 grout hole at 10 o'clock at 68.4'
 grout hole at 2 o'clock at 76.6'
 grout hole at 12 o'clock at 84.2'
 grout hole at 12 o'clock at 92'
 grout hole at 11 o'clock at 102'
 (1) day

29.	Asset Repair	MH 1 to I-2 (P-2) install interior band TBD & grout. (1-1/2) days	1	\$7,500.00	\$7,500.00
30.	Asset Repair	Raise manhole #13 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
31.	Asset Repair	Raise manhole #14 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
32.	Asset Repair	Raise manhole #15 to asphalt grade. (1/2) day	1	\$2,450.00	\$2,450.00
33.	Asset Repair	Raise manhole #16 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
34.	Asset Repair	Raise manhole #17 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
35.	Asset Repair	Raise manhole #23 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
36.	Asset Repair	Raise manhole #24 to grade. (1/2) day	1	\$1,850.00	\$1,850.00
37.	Services	Bond	1	\$6,458.00	\$6,458.00

Additional Days 5

Total

\$211,108.00

Note to customer

Southeast Services offers the above services in this proposal only. All proposals based on hourly rates are billed inclusive of travel time unless noted otherwise. Our proposal does not include Fuel surcharges, dump fees, retainage, surveys, engineering fees, as built, layouts, permits, M.O.T, sod replacement etc., unless otherwise noted.

Client is responsible for clean water supply and dump site for all vacuum truck jobs unless otherwise noted.

Southeast Services will charge to client any costs for special conditions (coverages) needed in regards to insurance requirements that are not standard within our policy.

Accepted date

Accepted by