



Symbiont Service Corp.
4372 North Access Road
Englewood, FL 34224

Phone: (941) 474-9306
Fax: (941) 473-9306
<https://symbiontservice.com/>

Quote Date: 8/14/2025

Bill to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Ship to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Quote #: q15974

Description	Quantity	Price	Amount
Pool Heater #1 Model: PH090ARDSWPM Serial: 1216155-K17	1	\$0.00	\$0.00
Replace reversing valve, TXV, filter drier and recharge system with 410a. *will not be able to complete repair until well work is completed*			
Warranty: One year parts and labor on the above repair	1	\$0.00	\$0.00
Replace Reversing Valve Symbiont Model 90	1	\$1,141.87	\$1,141.87
TXV,6T,R410A for 090 Aqua Cal	1	\$398.52	\$398.52
Labor Only Repair	1	\$148.50	\$148.50
Charge System With Puron R410A	8	\$86.40	\$691.20
Shipping and Handling	1	\$25.00	\$25.00
Misc. Shop Supplies	1	\$19.95	\$19.95

Subtotal: \$2,425.04

Tax: \$0.00

Total: \$2,425.04

You will save \$264.45 with your Agreement if accepted.



Symbiont Service Corp.
4372 North Access Road
Englewood, FL 34224

Phone: (941) 474-9306
Fax: (941) 473-9306
<https://symbiontservice.com/>

Quote Date: 8/14/2025

Bill to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Ship to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Quote #: q15975

Description	Quantity	Price	Amount
Pool Heater #2 Model: PH090ARDSWPM Serial: 1217262-L17	1	\$0.00	\$0.00
Replace compressor, TXV, start components and recharge system with 410a. *will not be able to complete repair until well work is completed*			
Warranty: One year parts and labor on the above repair	1	\$0.00	\$0.00
Replace compressor (PH090) ZP 70 208-230 VOLT 1ph *only includes 1 pound of freon lost from reclaiming*	1	\$3,951.19	\$3,951.19
Charge System With Puron R410A	7	\$86.40	\$604.80
Shipping and Handling	1	\$25.00	\$25.00
Misc. Shop Supplies	1	\$19.95	\$19.95

Subtotal: \$4,600.94

Tax: \$0.00

Total: \$4,600.94

You will save \$506.22 with your Agreement if accepted.



Symbiont Service Corp.
4372 North Access Road
Englewood, FL 34224

Phone: (941) 474-9306
Fax: (941) 473-9306
<https://symbiontservice.com/>

Quote Date: 8/14/2025

Bill to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Ship to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Quote #: q15976

Description	Quantity	Price	Amount
Pool Heater # 3 Model: PH090ARGSWPN Serial: 240200023 Quote to replace source in ball valve that is leaking Materials: -2" Reamer tool -2" Union -2" Ball Valve -1 2x2x1/2" Tee -1ft 2" PVC *will not be able to complete repair until well work is completed*	1	\$0.00	\$0.00
Warranty: One year parts and labor on the above repair	1	\$0.00	\$0.00
Union 2' S X S	1	\$61.92	\$61.92
2" PVC Ball Valve	1	\$89.50	\$89.50
2' X 2' X 1/2' S40 PVC Tee S X S X F	1	\$5.71	\$5.71
2" S40 PVC Pipe BE	1	\$3.68	\$3.68
Labor Only Repair	1	\$445.50	\$445.50
Shipping and Handling	1	\$25.00	\$25.00
Misc. Shop Supplies	1	\$19.95	\$19.95

Subtotal: \$651.26

Tax: \$0.00

Total: \$651.26

You will save \$67.36 with your Agreement if accepted.



Symbiont Service Corp.
4372 North Access Road
Englewood, FL 34224

Phone: (941) 474-9306
Fax: (941) 473-9306
<https://symbiontservice.com/>

Quote Date: 8/14/2025

Bill to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Ship to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Quote #: q15977

Description	Quantity	Price	Amount
Unit # 6 Model: PH090ARDSWPM Serial: 1216733-K17	1	\$0.00	\$0.00
Replace compressor, TXV, source side coil, start components, 2x2x1/2" tee and recharge system with 410a. *will not be able to complete repair until well work is completed*			
Warranty: One year parts and labor on the above repair	1	\$0.00	\$0.00
Replace compressor (PH090) ZP 70 208-230 VOLT 1ph *only includes 1 pound of freon lost from reclaiming*	1	\$3,951.19	\$3,951.19
85' Titanium Coil	1	\$748.12	\$748.12
2' X 2' X 1/2' S40 PVC Tee S X S X F	1	\$5.71	\$5.71
Labor Only Repair	1	\$259.88	\$259.88
Charge System With Puron R410A	7	\$86.40	\$604.80
Shipping and Handling	1	\$25.00	\$25.00
Misc. Shop Supplies	1	\$19.95	\$19.95

Subtotal: \$5,614.65

Tax: \$0.00

Total: \$5,614.65

You will save \$618.84 with your Agreement if accepted.



Symbiont Service Corp.
4372 North Access Road
Englewood, FL 34224

Phone: (941) 474-9306
Fax: (941) 473-9306
<https://symbiontservice.com/>

Quote Date: 8/14/2025

Bill to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Ship to
Gifford Aquatic Center
4895 43rd Avenue
Vero Beach, FL 32968

Quote #: q15978

Description	Quantity	Price	Amount
Unit # 5 Model: PH090ARDSWPM Serial: 1217268-L17 Replace source in PVC that is leaking Materials: -1ft 2" PVC -2" Ball Valve -2" 45 Coupling -1 2x2x1/2" Tee -2 2" Couplings *will not be able to complete repair until well work is completed* Warranty: One year parts and labor on the above repair	1	\$0.00	\$0.00
2" S40 PVC Pipe BE	1	\$3.68	\$3.68
2" PVC Ball Valve	1	\$89.50	\$89.50
2" S40 Pvc 45 S X S	1	\$4.84	\$4.84
2' X 2' X 1/2' S40 PVC Tee S X S X F	1	\$5.71	\$5.71
2' S40 PVC Coupling S X S	2	\$2.42	\$4.84
Labor Only Repair	1	\$297.00	\$297.00
Shipping and Handling	1	\$25.00	\$25.00
Misc. Shop Supplies	1	\$19.95	\$19.95

Subtotal: \$450.52

Tax: \$0.00

Total: \$450.52

You will save \$45.06 with your Agreement if accepted.