


Site Photographs – Wabasso Fishing Pier



Damaged Wabasso Fishing Pier in the foreground – Photo taken April 11, 2017

Site Photographs – Wabasso Fishing Pier East Structure



Damaged Wabasso Fishing Pier – East Structure – Photos taken April 13, 2017



Site Photographs – Wabasso Fishing Pier West Structure



Damaged Wabasso Fishing Pier – East and West Structure –
Photos taken April 13, 2017